

City of Green – NEXUS Environmental Observations

Date: 06/08/2018

Environmental Inspector(s): *Jim Gf*

Weather & Soil Conditions: Overcast; 66°F; 0-5 mph winds, dry/wet soils

Observed from: Road R/W Within NEXUS R/W

Item/Location	BMPs	Y	N	N/A	Notes
Street Cleaning	Street Cleaning Evident	X			Streets clean and free of sediment, power broom observed on Thursby during site visit.
	No Tracking Observed	X			
	Street Cleaning Equipment Staged	X			
Rock Entrances	Properly Topdressed	X			Additional gravel topdress applied to the construction access drives on Thursby since the last site visit.
	Check Dams in Ditchline	X			
Sediment Control Devices	Properly Installed	X			
	Functional	X			
	No Maintenance Recommended	X			
	No Additional SCD Recommended	X			
Stabilization Timeframes	No Areas Idle >14 Days	X			
	No Areas Near S and W Idle	X			
	No Additional TS Recommended	X			
Equipment Bridges	Fabric and Sideboards Intact	X			
	Equipment Gates Installed	X			
	Free of Sediment	X			
	No Maintenance Recommended	X			
Streams and Wetlands	Equipment Bridge Installed (S)	X			Topsoil in Wetland A14-112 on the east side of South Arlington Rd appears to have been segregated for road bore activity as visible from the roadway.
	Filter Fabric and Sideboards	X			
	Timber Mats Utilized (W)	X			
	Equipment Gates Re-installed	X			
	E/SCDs Installed and Functional	X			
	No Additional SCD Recommended	X			
	No Turbidity or Sedimentation	X			
General R/W	Impacts Avoided	X			Topsoil segregation and grading activity previously completed.
	Wood Chip Disposal	X			
	Topsoil Segregated	X			
	E/SCD Functional	X			
	No SCD Maintenance Needed	X			
	Good Housekeeping	X			
	Water Bars Installed	X			
	Proper Dewatering	X			
Road Bores	S&W Signage Installed	X			Road bore activity observed at Massillon Rd, Eastern Koons Rd, Western Koons Rd, S Arlington, Killinger, and S Main crossings. Bore activity appeared completed at Mayfair Rd and Greensburg Rd.
	Refueling Signage Installed	X			
	Topsoil Segregated	X			
	Proper Dewatering	X			
	Gravel Entrances Topdressed	X			
	Streets Clean	X			

BMP: Best Management Practice CWC: Concrete Wash Containment DB: Drivable Berm EB: Equipment Bridge ECM: Erosion Control Matting EG: Equipment Gate E/SCD: Erosion/Sediment Control Device FS: Filter Sock GH: Good Housekeeping GR: General Recommendation H/SR: Hard/Soft Restoration IP: Inlet Protection MD: Minimized Disturbance PRT: Potential Roost Tree RCE: Rock Construction Entrance S: Stream SB: Straw Bale SF: Silt Fence TM: Timber Mat TP: Trench Plug TS: Temporary Stabilization VB: Vegetated Buffer W: Wetland WB: Water Bar WSC: Wet-saw Slurry Containment

Key Observations: None

Notes:

The NEXUS R/W was observed from public roadways between Mayfair Rd and Main St.

Road bore activity observed at Massillon Rd, Eastern Koons Rd, Western Koons Rd, S Arlington, Killinger Rd, and S Main.

- Road bore at Mayfair and Greensburg Rd appeared completed.
- Topsoil in Wetland A14-112 on the east side of South Arlington Rd appears to have been segregated for road bore activity as visible from the roadway.

All remaining streams and wetlands that were visible from the roadway remained avoided.

- Erosion and sediment control devices appeared properly installed and functioning.
- No straw mulch was observed in wetlands that were visible from the roadway.

Erosion and sediment controls remained properly installed and functioning as needed.

- Regular maintenance of sediment control devices was evident.

General environmental observations from the site visit:

- Road bores were complete at Mayfair Rd and Greensburg Rd.
- Road bores were active at Massillon Rd, Eastern Koons Rd, Western Koons Rd, S Arlington, Killinger Rd, and S Main.
- The streets were clean and free of sediment.
- Rock construction entrances at roadway ingress/egress points appeared to be in working condition.
- Silt fence and/or Belted Silt Retention Fence (reinforced silt fence) appeared to remain properly installed and functional along wetland and stream boundaries, within residential areas, and downslope of several agricultural fields.
- Temporary stabilization was applied on idle topsoil piles and along the R/W.
- Timber mats remain installed at the equipment crossing locations of streams and wetlands. Temporary equipment gates were observed at all stream and wetland crossings that were visible from the roadway. Signage also remained installed at the wetlands and streams which included refueling guidance due to the presence of environmental resources.

Overall, our observations were satisfactory related to industry standards.

BMP: Best Management Practice **CWC:** Concrete Wash Containment **DB:** Drivable Berm **EB:** Equipment Bridge **ECM:** Erosion Control Matting **EG:** Equipment Gate **E/SCD:** Erosion/Sediment Control Device **FS:** Filter Sock **GH:** Good Housekeeping **GR:** General Recommendation **H/SR:** Hard/Soft Restoration **IP:** Inlet Protection **MD:** Minimized Disturbance **PRT:** Potential Roost Tree **RCE:** Rock Construction Entrance **S:** Stream **SB:** Straw Bale **SF:** Silt Fence **TM:** Timber Mat **TP:** Trench Plug **TS:** Temporary Stabilization **VB:** Vegetated Buffer **W:** Wetland **WB:** Water Bar **WSC:** Wet-saw Slurry Containment